



15.10 HiKey - CE AOSP RPB Test Report

Date	2015-11-06
Author(s)	Amit Khare, Linaro
Approvers	Tyler Baker, Linaro Milesz Wasilewski, Linaro Ricardo Salveti, Linaro
Build	Build Link
Release	2015.10

Configuration

Item	Explanation
Kernel	3.18.0+
Android version	6.0
Toolchain	4.9.x-google
Board Firmware Package	UEFI build #80

Glossary

Pass
Passing Partially
Fails

Manual Test Results

Test Run	Pass	Fail	Comments
Boot with eMMC	Pass		
Bluetooth- Scanning	Pass		
Bluetooth- Pairing	Pass		
Bluetooth- Audio Streaming	Pass		
Bluetooth- File transfer	Pass		
Serial Console	Pass		
HDMI- Hotplug	Pass		
HDMI- Display		Fails	Bug 136
HDMI- Audio		Fails	Bug 163
HDMI- Coldboot	Pass		
USB- ADB	Pass		
USB	Pass		
WiFi- Scanning	Pass		
WiFi- Profiles	Pass		
SD-HC	Pass		
Shutdown	Pass		
Sleep		Fails	Bug 161
Re-Boot	Pass		
LED	Pass		
Button		Fails	Bug 164

Open Bugs

Bug Description	Bug-id	Status
HDMI goes off while running CTS	136	CONF
[RPB] Fails to enter sleep mode	161	NEW
[RPB-AOSP] HDMI audio not working	163	NEW
[RPB-AOSP] Behaviors of power on button not following hardware user guide	164	CONF